

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2025

Submitted Date:

03/25/2025

Document Number:

715501465

**FIELD INSPECTION FORM**

Loc ID 314808 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10779  
Name of Operator: SCOUT ENERGY MANAGEMENT LLC  
Address: 13800 MONTFORT DRIVE SUITE 100  
City: DALLAS State: TX Zip: 75240

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Christian, Cody		Cody.Christian@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Saint, John		jsaint@scoutep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229636	WELL	PR	09/01/2017	OW	103-07293	HEFLEY, M E 6X	PR

**General Comment:**

[ECMC Inspection Report Summary](#)

On Tuesday, 03/25/2025, Compliance Inspector Kirby Burchett, completed a field inspection and audit at Scout Energy Management LLC on the Hefley, M E 6X well, Location #314808, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations no compliance issues were observed.

No follow up inspection is required.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	When no associated Tank battery is present at the Oil and Gas Location, the following information is required on the Well sign: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Well; Well name(s) and API number(s); The legal location of the Well(s) including the quarter/quarter section.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	(970) 675-3700		
Corrective Action:		Date:	_____

Overall Good:

**Spills:**

Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing/:**

Type	OTHER		
Comment:	Junction box and control panel Expanded metal		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Expanded metal		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 229636 Type: WELL API Number: 103-07293 Status: PR Insp. Status: PR

**Producing Well**

Comment: [January 2025 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Operator is responsible for maintaining Best Management Practices \(BMPs\) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501466	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974454">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974454</a>