

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404144000

Date Received:

03/27/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

ecmc.inspections@qb-energy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 718100310

Inspection Date: 03/17/2025

FIR Submit Date: 03/19/2025

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 335676

Location Name: NPR Number: K10-596 County: \_\_\_\_\_

Qtrqtr: NESW Sec: 10 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.627280 Longitude: -108.155610

### FACILITY - API Number: 05-045-00 Facility ID: 335676

Facility Name: NPR Number: K10-596

Qtrqtr: NESW Sec: 10 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.627280 Longitude: -108.155610

### CORRECTIVE ACTIONS:

1 CA# 203420

Corrective Action: Operator shall control emissions to prevent pollution and adverse impacts to air.

Date: 03/18/2025

Maintain tank equipment to comply with 608 Rules

Response: CA COMPLETED

Date of Completion: 03/18/2025

Operator  
Comment:

Replaced tank hatch to prevent emissions from venting and wildlife entry.

ECMC Decision: \_\_\_\_\_

Corrective Action:	Remove and properly dispose fluids within containmnet. Install or repair wildlife protection equipment.
--------------------	--

Response: CA COMPLETED

Operator Comment:	Removed all fluid from containment and disposed to maintain compliance. Installed wildlife BMP to prevent entry and comply with wildlife protection measurements of the ECMC.
-------------------	---

ECMC Decision:

Corrective Action: Comply with Rules 1002.c and 1002.f.

Response: CA COMPLETED

Operator Comment:	Pulled stockpile from perimeter storm water diversion ditch area to avoid risk of commingling with storm water runoff and sediment transport. Replaced erosion log to ensure fully functioning protection of stockpile.
-------------------	---

ECMC Decision:

Comment:

Print Name: Joseph Gracey Signed:

Title: Compliance Date: 3/27/2025 3:14:59 PM

<b><u>Document Number</u></b>	<b><u>Description</u></b>
404144003	Tank Hatch
404144005	Stockpile 1
404144006	Stockpile 2
404144008	Pigging Containment
404144009	Location Perimeter Ditch

Page 2 of 2