

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7101 From entrance to location



Photo # 7102 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7103 Location



Photo # 7104 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7105 Location



Photo # 7106 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7107 Location



Photo # 7108 Location





## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7109 Location



Photo # 7110 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7111 Location



Photo # 7112 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7113 Location



Photo # 7114 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7115 Location



Photo # 7116 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7117 Location



Photo # 7118 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7119 Staining near discharge coalescer




Photo # 7120 Staining near tank battery



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



**Photo # 7121 PRV vent line does not comply with CECMC pressure safety device rules (inlet scrubber/slug catcher)**



**Photo # 7122 PRV vent line does not comply with CECMC pressure safety device rules (inlet scrubber/slug catcher)**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



**Photo # 7123 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 7124 PRV vent line does not comply with CECMC pressure safety device rules**





## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7125 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 7126 PRV vent line does not comply with CECMC pressure safety device rules

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



**Photo # 7127 PRV vent line on compressor does not comply with CECMC pressure safety device rules**



**Photo # 7128 PRV vent line on compressor does not comply with CECMC pressure safety device rules**




## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



**Photo # 7129 PRV vent lines do not comply with CECMC pressure safety device rules**




**Photo # 7130 PRV vent lines do not comply with CECMC pressure safety device rules**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Mar 25, 2025 at 12:27:40 PM

**Photo # 7131 PRV vent lines do not comply with CECMC pressure safety device rules**



Mar 25, 2025 at 12:40:45 PM  
CO

**Photo # 7132 Tank battery lacks required signage**




## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



**Photo # 7133 Wildlife protection on chemical tank containment needs maintenance/wildlife hazard**



**Photo # 7134 Wildlife protection on chemical tank containment needs maintenance/wildlife hazard**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



**Photo # 7135 Wildlife protection on chemical tank containment needs maintenance/wildlife hazard**



**Photo # 7136 Wildlife protection on chemical tank containment needs maintenance/wildlife hazard**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



**Photo # 7137 Chemical tank lacks required labeling  
(Additionally operator Phone # disconnected & not in  
service)**



**Photo # 7138 Chemical tank lacks required labeling**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



**Photo # 7139 Chemical tank lacks required labeling  
(Additionally operator Phone # disconnected & not in service)**



**Photo # 7140 Chemical tank lacks required labeling  
(Additionally operator Phone # disconnected & not in service)**





## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



**Photo # 7141 Chemical tank lacks required labeling  
(Additionally operator Phone # disconnected & not in  
service)**



**Photo # 7142 Chemical tank lacks required labeling**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7143 Tank lacks required labeling



Photo # 7144 Tank lacks required labeling



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256



Photo # 7145 Tank lacks required labeling



Photo # 7146 Chemical tank lacks required labeling



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CASTLE SPRINGS COMPRESSOR STATION

Facility ID: 454256




Photo # 7147 Phone # disconnected & not in service



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources