

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2025

Submitted Date:

03/23/2025

Document Number:

698603341**FIELD INSPECTION FORM**Loc ID 304565 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265269	WELL	PR	02/08/2003	GW	125-08706	EYESTONE 5-35	PR

General Comment:

Follow-up Inspection. Inspector completed Follow-up inspection 03/17/2025 as required by FIR to ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 02/06/25 FIR document number 698603171. Corrective actions have not been performed or are insufficient to prevent recurrence. Assigned corrective action dates remains the same to document period of non-compliance.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	As cited in 02/06/25 FIR document number 698603171. Unable to determine volume. Fine sand has washed away under release area generally indicating leak has been ongoing. Corrective actions have not been performed or are insufficient to prevent recurrence.			
Corrective Action:	Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b. Assigned corrective action dates remains the same to document period of non-compliance.			Date: 02/12/2025

In Containment: No

Comment:

As cited in 02/06/25 FIR document number 698603171. Water line on the wellhead is leaking at the check valve.

Notified Field Forman 2/6/25 at 3:30 PM.

Notified Field Forman 3/17/25 at 2:31 PM.

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	As cited in 02/06/25 FIR document number 698603171. Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve open. Casing valve open. **Open ended valve on casing line**. Water line is leaking at the check valve. Corrective actions have not been performed or are insufficient to prevent recurrence. Notified Field Forman 2/6/25 at 3:30 pm. Notified Field Forman 3/17/25 at 2:31 PM.		
Corrective Action:	Inspect and service the wellhead, tree, and related surface control equipment to comply with Rule 603.c.(14). Assigned corrective action dates remains the same to document period of non-compliance.		Date: 02/07/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

