

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2025

Submitted Date:

03/25/2025

Document Number:

713602019

FIELD INSPECTION FORM

Loc ID: 487587 Inspector Name: COSTA, RYAN On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10797
Name of Operator: DESERT EAGLE OPERATING LLC
Address: 17330 PRESTON RD STE 200D-208
City: DALLAS State: TX Zip: 75252

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Bulf, Cathy		cathybulf@gmail.com	
Butler, Brad	972-345-9195	butleroil@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487587	LOCATION	AC			-	Red Rocks 1-09	CI

General Comment:

This is a construction inspection at the Red Rocks #1-09 location.
See all comments and attached photos for inspection observations.

Location Construction

Location ID: 487771 CDP: _____

Comment: Topsoil was salvaged along the access road and at the location. Near the location was large rocks at the surface and soils appeared to be sufficiently salvaged until too much rock was encountered. The piles were tracked for temporary stabilization. Topsoil piles will need to be seeded if stored for more than 6 months.

Corrective Action: _____ **Date:** _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ **Date:** _____

Wildlife BMPs:

Comment: Vegetation removal has occurred before the nesting period for migratory birds (April 1 to August 31).

Corrective Action: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
	No		No

Comments: Erosion BMPs: At the time of inspection there were no stormwater BMP's installed at the location. Stormwater controls need to be installed prior to construction.

Other BMPs: _____

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C **Date:** 03/28/2025

5

Comment: _____

Corrective Action: _____ **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404140782	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974202
713602020	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6974197