

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2025

Submitted Date:

04/03/2025

Document Number:

699700469

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ Heil, John \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Gardner, Mike		mgardner@terraep.com	
Longworth, Mike		mike.longworth@state.co.us	
Cholas, Nick		nick.cholas@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
464634	PRODUCED WATER TRANSFER SYSTEM	AC	09/27/2022		-	Silt Produced Water 464634	EI

**General Comment:**

ECMC Environmental Inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities									
Facility ID:	464634	Type:	PRODUCED	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: See Initial Form 19 Doc #404137774, Supplemental Form 19 Doc #404145198, Inspection Doc #699700463 and Inspection Doc #699700467 for more information. Spill/Release occurred within High Priority Habitats (HPH) (Effective July 15, 2024). ECMC staff John Heil conducted an Environmental Inspection of the spill/release point and the surrounding areas. The temporary polyline identified in Inspection Doc #699700467 was still present at time of inspection. The majority of the stock pond had been emptied by pumping fluids through the temporary polyline and the operator was utilizing vac trucks to remove the remaining fluids. A 12-inch PVC line was observed conveying water from the unnamed tributary to Dry Hollow Creek. INITIAL MITIGATION Doc #404145865 states "Additionally, a temporary 12-inch PVC line was attached to the discharge end of a culvert at the inlet to the pond and installed along the north side of the pond, diverting water within the unnamed drainage to flow into an earthen division ditch to Dry Hollow Creek." Water samples of the outflow of the 12-inch PVC indicate compliance with table 915-1 Organic and Inorganic Compounds in Groundwater (see Flume Outlet results on ANALYTICAL DATA SUMMARY TABLE(S) Doc #404145308.) Fluids and stained soils were still present on the west side of Co Rd 331 and stained soils were also present adjacent to the unnamed tributary of Dry Hollow Creek on the west side of Co Rd 331. See attached Photo Log for details.

Corrective Action: Operator shall remove and dispose of all fluids and stained soils located on the west side of Co Rd 331. These include the soils adjacent the unnamed tributary of Dry Hollow Creek.

Date: \_\_\_\_\_

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water:

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700470	20250325 Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6989883">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6989883</a>