

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404132494

Date Received:  
04/10/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

| Contact Name          | Phone | Email                                     |
|-----------------------|-------|---|
| <u>Popejoy, Dusty</u> |       | <u>dusty.popejoy@state.co.us</u>          |
| <u>.TEP</u>           |       | <u>COGCCInspectionReports@terraep.com</u> |

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303542  
Inspection Date: 03/05/2025 FIR Submit Date: 03/07/2025 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334949

Location Name: LINDAUER-67S96W Number: 11NENE County:  
Qtrqtr: NENE Sec: 11 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.456367 Longitude: -108.072167

FACILITY - API Number: 05-045-00 Facility ID: 334949

Facility Name: LINDAUER-67S96W Number: 11NENE  
Qtrqtr: NENE Sec: 11 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.456367 Longitude: -108.072167

CORRECTIVE ACTIONS:

1 CA# 203107

Corrective Action: Install signs to comply with Rule 605.d. Date: 04/07/2025

Response: CA COMPLETED Date of Completion: 03/31/2025

Operator Comment: Wellhead signs have been replaced. Corrective Action complete.

ECMC Decision:

ECMC Representative:

2 CA# 203108

Corrective Action: Replace label to comply with Rule 605.h.

Date: 04/07/2025

Response: CA COMPLETED

Date of Completion: 03/10/2025

Operator Comment: Methanol tank label has been replaced. Corrective Action complete.

ECMC Decision:

ECMC Representative:

3 CA# 203109

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/16/2025

Response: CA COMPLETED

Date of Completion: 03/25/2025

Operator Comment: Check dams have been refreshed. Corrective Action complete.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #203107: Wellhead signs have been replaced. Corrective Action complete. CA #203108: Methanol tank label has been replaced. Corrective Action complete. CA #203109: Check dams have been refreshed. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 4/10/2025 9:34:53 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

Document Number Description

Table with 2 columns: Document Number, Description. No data rows are present.

Total Attach: 0 Files