

## **Storm Water Management and Erosion control**

**Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 D**

**Location # 324014**



**Location Overview: Location is within High  
Priority/Density/NSO/Black Bear Habitat areas.**

**Section/Township/Range: 30 6S91W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 D**  
**Location # 324014**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 D**  
**Location # 324014**



**Photo # 92 Failure to minimize erosion & transport of sediment on lease road/road degradation**



**Photo # 93 Failure to minimize erosion & transport of sediment on lease road/road degradation**



**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 D**  
**Location # 324014**



**Photo # 94 Failure to minimize erosion & transport of sediment on lease road/road degradation**



**Photo # 95 Failure to minimize erosion & transport of sediment on lease road/road degradation**



**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 D**  
**Location # 324014**



**Photo # 96 Failure to minimize erosion & transport of sediment on lease road/road degradation**



**Photo # 97 Failure to minimize erosion & transport of sediment on lease road/road degradation**



**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 D**  
**Location # 324014**



**Photo # 98 Failure to minimize erosion & transport of sediment on lease road/road degradation**



**Photo # 99 Failure to minimize erosion & transport of sediment on lease road/road degradation**



**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 D**  
**Location # 324014**



**Photo # 100 Failure to minimize erosion & transport of sediment on lease road/road degradation**



**Photo # 101 Failure to minimize erosion & transport of sediment on lease road/road degradation**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 15-30 D**  
**Location # 324014**



**Photo # 102 Failure to minimize erosion & transport of sediment on lease road/road degradation**