

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2025

Submitted Date:

04/14/2025

Document Number:

713602062

**FIELD INSPECTION FORM**

Loc ID 321659 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96730  
Name of Operator: WILLIFORD ENERGY COMPANY  
Address: 6060 AMERICAN PLAZA SUITE 760  
City: TULSA State: OK Zip: 74135

**Findings:**

- 6 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Enforcement, ECMC		dnr_ecmcenforcement@state.co.us	
GROWNS LARRY		growns@willifordenergy.com	
Storts, Doug		pds@willifordenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207701	WELL	PR	11/11/2008	OW	017-06636	RHOADES UNIT 4-5	RI

**General Comment:**

This is a follow up of the previous inspections; #713600865, #713601097, #713601337, #713601841.  
The corrective actions of the previous inspections have not been completed.  
Non-compliance with the Rules will be referred to enforcement.  
Operator is directed to perform corrective actions outlined on this inspection report immediately.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	There are areas where vehicles have driven outside of the access road boundary causing unnecessary disturbance that will need to be reclaimed. There are areas of the access road that are not maintained. Repeated or flagrant instance(s) of failure to restrict lease access to lease roads which result in unreasonable land damage or crop losses shall be subject to a penalty under Rule 523.		
Corrective Action:	Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e rule.	Date:	

Overall Good:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	_____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Wildlife protection (netting) needs to be placed at the secondary containment to prevent entry into oily fluids. See photo #4.		
Corrective Action:	Comply with Rule 902.b.	Date:	
Type	OTHER		
Comment:	The electric utility has been repaired. The old wire and debris remains and needs to be removed. Previous CA was not completed.		
Corrective Action:	Comply with rule 606.	Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	WELLHEAD		
Comment:	There are oil stained soils at the wellhead that needs to be cleaned up. Previous Corrective Action was not completed.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date:

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are areas of access road which are not stabilized or maintained. There are areas where stormwater is pooling and vehicles are driving around the impacted road causing unnecessary disturbance. The access road needs to be repaired and maintained with BMP's such as road base and culverts. The roads needs to be built up to allow stormwater drainage. Previous corrective action was not completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713602063	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7004122">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7004122</a>