

<u>Company</u>	SCOUT	
<u>Field Name</u>	RANGELY	
<u>Location</u>	NESW Section 14,T2N,R103W, 6TH P.M.	
<u>Short Name</u>	AMC38	
<u>County & State</u>	Rio Blanco, CO	
<u>API No.</u>	05-103-06322	10 3/4" casing patch
<u>Updated by</u>	Austin Mayer	7" casing patch from
<u>Date of Diagram</u>	4/9/2025	Tight 7" casing @ 31
<u>Kelly Bushing</u>	5,506'	
<u>Ground Level</u>	5,496'	
<u>Spud Date:</u>	4/12/1948	
<u>Completion Date:</u>	5/26/1948	

Casing Leak Details

10 3/4" casing patch from surface to 329' (6/77)
7" casing patch from surface to 525' (6/77)
Tight 7" casing @ 311' (3/94)


Production Linear 1			
Size	Weight	Grade	Depth
Year	Sx. Cmt.	Circulate	TOC @

Upper Perf _____
Lower Perf _____
Open Hole 6312-6657

Current Completion

Formation Tops

T/Niobrara	2400
B/Niobrara	2580
T/Frontier	3340
T/Frontier 1st Sand	3425
T/Mowry	3619
T/Dakota	3699
T/Morrison	3792
T/Curtis	4493
T/Entrada	4600
T/Carmel	4741
T/Navajo	4796
T/Chinle	5430
T/Shinarump	5540
T/Moenkopi	5630
T/L Moenkopi	5859
T/L Weber	6305



PBTD: 6,657'
TD: 6,657'

Cement

Weber

Fill