

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404167212

Date Received:  
04/16/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Luke Kelly	970-939-6353	lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718700173  
Inspection Date: 03/05/2025 FIR Submit Date: 03/10/2025 FIR Status:

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 431184

Location Name: Pronghorn Number: T-3 Pad County:  
Qtrqr: SESE Sec: 3 Twp: 5N Range: 61W Meridian: 6  
Latitude: 40.424300 Longitude: -104.189430

FACILITY - API Number: 05-123-00 Facility ID: 431184

Facility Name: Pronghorn Number: T-3 Pad  
Qtrqr: SESE Sec: 3 Twp: 5N Range: 61W Meridian: 6  
Latitude: 40.424300 Longitude: -104.189430

CORRECTIVE ACTIONS:

1 CA# 203135

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D. Date: 03/15/2025

Response: CA COMPLETED Date of Completion: 04/16/2025

Operator Comment: Operator has address the reported issue in order to comply with Rule 1002.f.(2).D.

ECMC Decision:

ECMC  
Representative:

2 CA# 203136

Corrective Action: Comply with Rule 1003. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: \_\_\_\_\_

Response: CA COMPLETED \_\_\_\_\_

Date of Completion: 04/16/2025

Operator  
Comment:

Operator has applied hydromulch and reseeded in order to comply with Rule 1004.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aubrey Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 4/16/2025 11:53:50 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404167224	Inspection Resolution
-----------	-----------------------

Total Attach: 1 Files