

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/A Pad

Location ID: 421223

Date: 4/16/2025



Location Overview – Photo #08154



Location – Photo #08155

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/A Pad

Location ID: 421223

Date: 4/16/2025



Location – Photo #08157



Location – Photo #08165

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/A Pad

Location ID: 421223

Date: 4/16/2025



Inaccurate API Number on Wellhead Sign – Photo #08156



Unmarked Deadman – Photo #08177

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/A Pad

Location ID: 421223

Date: 4/16/2025



Wildlife Entry Hazard on Out-of-Service Separator – Photo #08158



Wildlife Entry Hazard on Out-of-Service Separator – Photo #08159

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/A Pad

Location ID: 421223

Date: 4/16/2025



Wildlife Entry Hazard on Out-of-Service Separator – Photo #08160



Wildlife Entry Hazard on Out-of-Service Separator – Photo #08161

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/A Pad

Location ID: 421223

Date: 4/16/2025



Wildlife Entry Hazard on Out-of-Service Separator – Photo #08162



Damaged Berm Liner – Photo #08168

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, McLin/A Pad

Location ID: 421223

Date: 4/16/2025



Damaged Berm Liner – Photo #08174



Damaged Berm Liner – Photo #08175