

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



**Location Overview: Location is within High
Priority/NSO/Black Bear Habitat areas.
Section/Township/Range: 10 7S91W**



Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



Photo # 6258 From inspection 708906071 conducted on 03/20/2025 Erosion & transport of sediment off location /berm needs maintenance



Photo # 2891 Erosion & transport of sediment off location /berm needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



Photo # 6259 From inspection 708906071 conducted on 03/20/2025 Erosion & transport of sediment off location /berm needs maintenance



Photo # 2892 Erosion & transport of sediment off location /berm needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



Photo # 6260 From inspection 708906071 conducted on 03/20/2025 Erosion & transport of sediment off location /berm needs maintenance



Photo # 2893 Erosion & transport of sediment off location /berm needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



Photo # 6261 From inspection 708906071 conducted on 03/20/2025 Erosion & transport of sediment off location /berm needs maintenance



Photo # 2894 Erosion & transport of sediment off location /berm needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



**Photo # 2895 Erosion & transport of sediment off location
/berm needs maintenance**



**Photo # 2896 Erosion & transport of sediment off location
/berm needs maintenance**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



**Photo # 2897 Erosion & transport of sediment off location
/berm needs maintenance**



**Photo # 2898 Erosion & transport of sediment off location
/berm needs maintenance**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



**Photo # 2899 Erosion & transport of sediment off location
/berm needs maintenance**



**Photo # 2900 Erosion & transport of sediment off location
/berm needs maintenance**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



Photo # 6262 From inspection 708906071 conducted on 03/20/2025 Erosion & transport of sediment off location /berm needs maintenance



Photo # 2901 Erosion & transport of sediment off location /berm needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



Photo # 6263 From inspection 708906071 conducted on 03/20/2025 Erosion & transport of sediment off location /berm needs maintenance



Photo # 2902 Erosion & transport of sediment off location /berm needs maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



**Photo # 2903 Erosion & transport of sediment off location
/berm needs maintenance**



**Photo # 2904 Erosion & transport of sediment off location
/berm needs maintenance**

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain CSF-67S91W 10NESW Pad
Location # 322442



Photo # 2905 Erosion & transport of sediment off location
/berm needs maintenance