

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



Photo # 2187 From entrance to location




Photo # 2188 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad  
Location # 417399



Photo # 2189 Location



Photo # 2190 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



Photo # 2191 Location



Photo # 2192 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad  
Location # 417399



Photo # 2193 Location



Photo # 2194 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



Photo # 2195 Location



Photo # 2196 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad  
Location # 417399



Photo # 2197 Location



Photo # 2198 Location



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399




Photo # 2199 Location



Photo # 2200 Location

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



Apr 16, 2025 at 2:35:48 PM  
CO

**Photo # 2201 Methanol tank label lacks required information/not in compliance with CECMC rules**



Apr 16, 2025 at 2:35:43 PM  
CO

**Photo # 2202 Methanol tank label lacks required information/not in compliance with CECMC rules**



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



**Photo # 2203 Methanol tank label lacks required information/not in compliance with CECMC rules**



**Photo # 2204 Glycol tank label lacks required information/not in compliance with CECMC rules**

## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



**Photo # 2205 Glycol tank label lacks required information  
/not in compliance with CECMC rules**



**Photo # 2206 Glycol tank label lacks required information  
/not in compliance with CECMC rules**



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



**Photo # 2207 Compressor oil tank label lacks required information/not in compliance with CECMC rules**



**Photo # 2208 Compressor oil tank label lacks required information/not in compliance with CECMC rules**



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



Photo # 2209 Compressor oil tank label lacks required information/not in compliance with CECMC rules




Photo # 2210 Tank label weathered & damaged/some required information is illegible/not in compliance with CECMC rules



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



Photo # 2211 Tank label weathered & damaged/some required information is illegible/not in compliance with CECMC rules



Photo # 2212 Tank label weathered & damaged/some required information is illegible/not in compliance with CECMC rules



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



**Photo # 2213 Unused equipment (additionally there's open ended piping on the unused equipment which constitutes a wildlife hazard)**



**Photo # 2214 Open ended piping on the unused equipment which constitutes a wildlife hazard/available for entry by wildlife**



## Inspection/Audit Photos

Location Name: TEP Rocky Mountain GGU FED (MDP PAD #10) 23A-20-691 Pad

Location # 417399



Photo # 2215 Unused Equipment