



COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100				
API No. 05- <u>001 - 08328</u>	LEASE NAME: <u>Bass Box Elder 6-32</u>				
LOCATION: <u>SW SE 6-35-6SW</u>	OPERATOR: <u>Thofare Res</u>				
DATE: <u>3/27/98</u>	INSPECTOR: <u>LAR</u>				
Insp. Type: <u>BH</u>	Insp. Status: <u>PA</u>	PA: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	Pass/Fail: P <input type="checkbox"/> F <input checked="" type="checkbox"/>	Viol.: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	NOV: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)	<u>Testing bradenhead to determine if 2nd stage cement job made it up into surface casing. Attempted to pressure up to 500 psi, wouldn't hold</u>	
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous	<u>Well is in the process of being plugged CIBP set at 8250' to isolate perfs CIBP set at 1830' (10' below DV tool) w/ 2.5x cement placed on bridge plugs</u>	

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By: _____ Date Remedied: _____

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.