

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404174195

Date Received:  
04/22/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:  
2 of 2 CAs from the FIR responded to on this Form  
2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10840  
Name of Operator: ABUNDANCE ENERGY SERVICES LLC  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

**Additional Operator Contact:**

Contact Name	Phone	Email
		<a href="mailto:aprice@abundance-energy.com">aprice@abundance-energy.com</a>
		<a href="mailto:sjbcompliance@abundance-energy.com">sjbcompliance@abundance-energy.com</a>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 714002063  
Inspection Date: 04/08/2025 FIR Submit Date: 04/09/2025 FIR Status:

**Inspected Operator Information:**

Company Name: ABUNDANCE ENERGY SERVICES LLC Company Number: 10840  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114

**LOCATION - Location ID: 325156**

Location Name: FORD-OLSON UNIT-N33N8W Number: 9SESE County:  
Qtrqtr: SESE Sec: 9 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.115040 Longitude: -107.718350

**FACILITY - API Number: 05-067- -00 Facility ID: 325156**

Facility Name: FORD-OLSON UNIT-N33N8W Number: 9SESE  
Qtrqtr: SESE Sec: 9 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.115040 Longitude: -107.718350

**CORRECTIVE ACTIONS:**

1 CA# 203950

Corrective Action: Conduct revegetation/reseeding efforts within portions of the interim reclamation area with bare soils and sparse vegetation. Date:

Response: CA COMPLETED Date of Completion: 04/15/2025

Operator Comment: Quote has been received and accepted for work to amend soil types, seed and apply erosion control. Work will be performed in advance of expected moisture so that seed will grow.

ECMC Decision:

ECMC  
Representative:

2 CA# 203951

Corrective Action: Storm water BMPs and erosion controls (ie: ecofiber, straw mulch, erosion control blankets, etc.) need to be installed and maintained on portions of the project area sparse and bare soils until soils are stabilized with desirable perennial vegetation.

Date: 04/23/2025

Response: CA COMPLETED

Date of Completion: 04/15/2025

Operator Comment: Quote has been received and accepted for work to amend soil types, seed and apply erosion control. Work will be performed in advance of expected moisture so that seed will grow.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached for Remedial Report and quote for work to be done by Ridgeline.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: \_\_\_\_\_

Title: Engineering Analyst

Date: 4/22/2025 12:27:12 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404174195	FIR RESOLUTION SUBMITTED
404174214	Remedial Report
404174218	Quote for work to be done

Total Attach: 3 Files