

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2025

Submitted Date:

04/24/2025

Document Number:

710500485

**FIELD INSPECTION FORM**

Loc ID 307865 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258244	WELL	PR	07/01/2012	CBM	071-07087	GROUSE 13-36	EI
488964	SPILL OR RELEASE	AC	03/11/2025		-	Grouse 13-36 Spill	EI

**General Comment:**

This is a follow up Environmental Inspection to Field Inspection Doc #710500420 for the Grouse 13-36, well location located in Las Animas County, Co. Spill ID 488964

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Well Placard located on meter house, WDID sticker is illegible Install sign to comply with Rule 605.g.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			
Lube Oil	WELLHEAD				
Comment:	Stained Soils located within guarding for wellhead and engine skids				
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			Date:	05/09/2025

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 258244 Type: WELL API Number: 071-07087 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 488964 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spill/Remediation:**

Comment: This is a follow up inspection for Spill ID 488964, at the time of inspection gathering line valve was repaired. No visual signs of impacts to soils observed along the spill path, Operator shall continue spill remediation in accordance with Rule 912.b and Rule 913.

Form 27-i Document # 404156707 Filed on 4/08/2025

Operator shall provide quarterly spill remediation updates in accordance with Rule 913.

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500486	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7021815">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7021815</a>