

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2025

Submitted Date:

04/29/2025

Document Number:

697602484

FIELD INSPECTION FORM

Loc ID 312242 Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 55030
Name of Operator: MCCARTNEY ENGINEERING LLC
Address: 4251 KIPLING ST STE 575
City: WHEAT RIDGE State: CO Zip: 80033

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
McCartney, Lisa		lisa@mccartneyengineering.com	
McCartney, Ron		ron@mccartneyengineering.com	All Inspections
Waggoner, Kyle		kyle.waggoner@state.co.us	
McCartney, Jack	303-830-7208	jack@mccartneyengineering.com	
Heibel, Krystal		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
116281	PIT	AC			-	RICE	EI
312242	LOCATION	AC			-	RICE-612N54W 33SWNW	EI

General Comment:

ECMC Environmental Inspection to determine progress on Rice-612N54W 33SWNW (Location ID 312242) and Pit #116281. Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

[Refer to the previous Environmental Inspection Doc#709100135 for more information.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:					
Type	Area	Volume			
Crude Oil	Tank				
Comment: Hydrocarbon staining at the top of tank.					
Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.					Date: <u>05/29/2025</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Secondary containment is inadequate to contain 150% of the volume of the largest tank. All earthen berms shall be able to contain any release at the site.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: <u>05/29/2025</u>

Venting:

Yes/No	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
	Date: <input type="text"/>

Inspected Facilities

Facility ID: 116281 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 312242 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Operator shall submit a Form 15 forPpit (#116281) due to existing Form 15 (Doc# 400594353) being "on hold" and under name of previous operator (CM Production, LLC)

Corrective Action: Submit an eForm 15 Pit Report to update ECMC records with current information to comply with rule 908.a.

Date: 11/13/2023

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action:

Date: _____

ECMC Comments

Comment	User	Date
Operator shall submit a Form 27 Supplemental for each Remediation Project to be in accordance with Rule 913.e.(3).	ahmadiaa	04/29/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602488	Photolog	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7027041