

# State of Colorado Energy & Carbon Management Commission



Document Number:  
404185710

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:  
04/30/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:  
1 of 1 CAs from the FIR responded to on this Form  
1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10720  
Name of Operator: KODA EXPLORATION LLC  
Address: 2443 SOUTH UNIVERSITY BLVD 215  
City: DENVER State: CO Zip: 80210  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>ELGERD ANDERS</u>		<u>elgerd@comcast.net</u>
<u>REZENDES, JOSEPH</u>		<u>rezenjp@gmail.com</u>
<u>SULLIVAN RYAN</u>		<u>rsullivantc@gmail.com</u>
<u>NOONAN, ASHLEY</u>		<u>anoonan@progressivepcs.net</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601850  
Inspection Date: 02/04/2025 FIR Submit Date: 02/05/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KODA EXPLORATION LLC Company Number: 10720  
Address: 2443 SOUTH UNIVERSITY BLVD 215  
City: DENVER State: CO Zip: 80210

LOCATION - Location ID: 472992

Location Name: Roaring Fork Number: 14-28 Pad County: LINCOLN  
Qtrqtr: SESW Sec: 28 Twp: 16S Range: 54W Meridian: 6  
Latitude: 38.627090 Longitude: -103.460720

FACILITY - API Number: 05-073-00 Facility ID: 472941

Facility Name: Roaring Fork Number: 14-28  
Qtrqtr: SESW Sec: 28 Twp: 16S Range: 54W Meridian: 6  
Latitude: 38.627090 Longitude: -103.460720

CORRECTIVE ACTIONS:

**1** CA# 202367

Corrective Action: Comply with 1004 Rules Date: 03/31/2025  
Response: CA COMPLETED Date of Completion: 04/07/2025

Hearing Docket # 240500113, submitted 5/9/2024 is currently in "Director Review" Status for a Variance Request per Surface Owner request to allow for the following: The Surface Owner(s) directed

Operator  
Comment:

that the two-track access road be left as-is during and after KODA's planned operations at the wellsite to allow continued access to their livestock/grazing operation. The entryway and gate to the two-track access road were installed by KODA. The Surface Owner(s) would like to keep the entryway, gate and two-track access road in place as it is an upgrade to their land.

The location was spot seeded only in the bare spots to minimize disturbing the already established grass that was planted previously utilizing a no-till drill seeder. Seed Mix was purchased from Granite Seed (Denver), utilizing 72 bulk pounds (65 PLS = Pure Live Seed). Post seeding photos attached.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: This FIRR is being submitted to update the ECMC staff that re-seeding has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 4/30/2025 5:00:31 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404185742	Response Photos

Total Attach: 1 Files