

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404185679

Date Received:

04/30/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10720

Name of Operator: KODA EXPLORATION LLC

Address: 2443 SOUTH UNIVERSITY BLVD 215

City: DENVER State: CO Zip: 80210

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
SULLIVAN, RYAN		rsullivantc@gmail.com
NOONAN, ASHLEY		anoonan@progressivepcs.net
ELGERD, ANDERS		elgerd@comcast.net
REZENDES, JOSEPH		rezenjp@gmail.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601852

Inspection Date: 02/04/2025

FIR Submit Date: 02/05/2025

FIR Status: _____

Inspected Operator Information:

Company Name: KODA EXPLORATION LLC

Company Number: 10720

Address: 2443 SOUTH UNIVERSITY BLVD 215

City: DENVER State: CO Zip: 80210

LOCATION - Location ID: 477611

Location Name: WHP Misty Number: 2-7 Pad County: LINCOLN

Qtrqr: NWNE Sec: 7 Twp: 17S Range: 54W Meridian: 6

Latitude: 38.593580 Longitude: -103.492650

FACILITY - API Number: 05-073-00 Facility ID: 477612

Facility Name: WHP Misty Number: 2-7

Qtrqr: NWNE Sec: 7 Twp: 17S Range: 54W Meridian: 6

Latitude: 38.593580 Longitude: -103.492650

CORRECTIVE ACTIONS:

1 CA# 202366

Corrective Action: Comply with 1004 Rules

Date: 03/31/2025

Response: CA COMPLETED

Date of Completion: 04/07/2025

Hearing Docket # 240400085, submitted 04/10/2024 is currently in "Director Review" Status for a Variance Request per Surface Owner request to allow for the following:

Operator
Comment:

The Surface Owner(s) directed that the two-track access road be left as-is during and after KODA's planned operations at the wellsite to allow continued access to their livestock/grazing operation. The entryway and gate to the two-track access road were installed by KODA. The Surface Owner(s) would like to keep the entryway, gate and two-track access road in place as it is an upgrade to their land.

The location was reseeded utilizing a no-till drill seeder. Seed Mix was purchased from Granite Seed (Denver), utilizing 125 bulk pounds (116 PLS = Pure Live Seed). Post seeding photos attached.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This FIRR is being submitted to update the ECMC staff that re-seeding has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Regulatory Analyst

Date: 4/30/2025 4:58:37 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404185679	FIR RESOLUTION SUBMITTED
404185696	RESPONSE PHOTOS

Total Attach: 2 Files