

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404179278

Date Received:
05/12/2025

Spill report taken by:
Metz, Collin

Spill/Release Point ID:
489263

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 515-0055</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>		Mobile: <u>()</u>
Contact Person: <u>Jaron Bartoszek</u>		Email: <u>DJRemediation_Forms@oxy.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 404072710

Initial Report Date: 01/28/2025 Date of Discovery: 01/28/2025 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR NWSE SEC 9 TWP 2N RNG 66W MERIDIAN 6

Latitude: 40.150810 Longitude: -104.778527

Municipality (if within municipal boundaries): _____ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No 435886

Spill/Release Point Name: Aggregate State 24 22 25-9 HZ O SA Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): <u>Unknown</u>	Estimated Condensate Spill Volume(bbl): <u>Unknown</u>
Estimated Flow Back Fluid Spill Volume(bbl): <u>0</u>	Estimated Produced Water Spill Volume(bbl): <u>Unknown</u>
Estimated Other E&P Waste Spill Volume(bbl): <u>0</u>	Estimated Drilling Fluid Spill Volume(bbl): <u>0</u>

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: ~18 degrees F, sunny

Surface Owner: FEE

Other(Specify): _____

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On January 28, 2025, a release was discovered at the Aggregate State 24 22 25-9 HZ O SA location. The cause of the release was due to a dump line failure at the separator. Site assessment and excavation activities are ongoing and are summarized in the Form 27-Supplemental Site Investigation and Remediation Workplan under Remediation Project No. 40391 (approved Form 27-Initial Document No. 404157128). A topographic Site Location Map showing the geographic location setting of the release is provided as Figure 1.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
1/28/2025	Surface Owner	APC	--phone	
1/28/2025	Weld County	B. Cavanagh	--email	
1/28/2025	Weld County	R. Burton	--email	
1/28/2025	Weld County	R. Rudisill	--email	

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: _____ Public Water System: _____
 Residence or Occupied Structure: _____ Livestock: _____
 Wildlife: _____ Publicly-Maintained Road: _____

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery _____ (HH:MM)
 Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
 Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
 Enter the Document Number of the Initial Accident Report, Form 22 _____
 Was there damage during excavation? _____
 Was CO 811 notified prior to excavation? _____

Yes Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): _____ 10 _____

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

The presence of free product or hydrocarbon sheen Surface Water

The presence of free product or hydrocarbon sheen on Groundwater

The presence of contaminated soil in contact with Groundwater

The presence of contaminated soil in contact with Surface water

Yes Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.

No Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.

Areas offsite of Oil & Gas Location Off-Location Flowline right of way

No Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.

No Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>05/12/2025</u>		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	_____	_____	<input checked="" type="checkbox"/>
CONDENSATE	_____	_____	<input checked="" type="checkbox"/>
PRODUCED WATER	_____	_____	<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) Soil Groundwater Surface Water Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 16 Width of Impact (feet): 13

Depth of Impact (feet BGS): 10 Depth of Impact (inches BGS): _____

How was extent determined?

On January 28, 2025, a release was discovered at the Aggregate State 24 22 25-9 HZ O SA location. The cause of the release was due to a dump line failure at the separator due to freezing temperatures. On February 26, 2025, nine confirmation soil samples were collected following excavation activities and submitted for laboratory analysis of the full Table 915-1 analytical suite. Analytical results for soil sample SS-01@10' indicated that the TPH, BTEX, 1,2-methyl, naphthalene, fluorene, TMBs, and arsenic concentrations exceeded the applicable ECOMC Table 915-1 protection of groundwater soil standards. Excavation and assessment activities are ongoing and will be summarized in the Form 27-Supplemental Site Investigation and Remediation Workplan under Remediation Project No. 40391 (approved Form 27-Initial Document No. 404157128). Groundwater has not been encountered during the initial cleanup and site assessment activities. If groundwater is encountered during ongoing excavation and assessment activities, a minimum of one grab sample will be collected as soon as practical. Groundwater samples will be submitted to an accredited laboratory for all analytes listed in ECOMC Table 915-1 Organic Compounds in Groundwater (BTEX, naphthalene, 1,2,4- and 1,3,5- TMB) and Groundwater Inorganic Parameters (total dissolved solids (TDS), chloride, and sulfate) using standard methods. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1. The soil sample locations are illustrated on Figure 2. Soil sample location and field screening data are provided in Table 1. Soil analytical results are summarized in Tables 2-5. The laboratory analytical reports are attached. Field notes and a photographic log are provided as Attachment A. The State Notification email is provided as Attachment B.

Soil/Geology Description:

gravely Clay (GC)

Depth to Groundwater (feet BGS) 15

Number Water Wells within 1/2 mile radius: 19

If less than 1 mile, distance in feet to nearest

Water Well 1896 None

Surface Water 848 None

Wetlands 815 None

Springs _____ None

Livestock 2005 None

Occupied Building 1838 None

Additional Spill Details Not Provided Above:

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 05/12/2025

Root Cause of Spill/Release Equipment Failure

Other (specify) _____

Type of Equipment at Point of Spill/Release: Dump Line

If "Other" selected above, specify or describe here:

Describe Incident & Root Cause (include specific equipment and point of failure)

The cause of the equipment failure was due to a frozen separator dump line that split and released produced fluids.

Describe measures taken to prevent the problem(s) from reoccurring:

The affected infrastructure is being permanently removed and replaced. The use of separator heating equipment, and heat trace wiring will be inspected to ensure it is operational, and used during freezing weather periods.

Volume of Soil Excavated (cubic yards): _____

Disposition of Excavated Soil (attach documentation) Offsite Disposal Onsite Treatment

Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): _____

Volume of Impacted Surface Water Removed (bbls): _____

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached, check all that apply)

Horizontal and Vertical extents of impacts have been delineated.

Documentation of compliance with Table 915-1 is attached.

All E&P Waste has been properly treated or disposed.

Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: 40391

SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Jaron Bartoszek

Title: Environmental Advisor Date: 05/12/2025 Email: DJRemediation_Forms@oxy.com

COA Type**Description**

0 COA	

ATTACHMENT LIST**Att Doc Num****Name**

404181325	SITE MAP
404181327	SOIL SAMPLE LOCATION MAP
404181332	LABORATORY ANALYTICAL REPORT
404181335	LABORATORY ANALYTICAL REPORT
404181337	PHOTO DOCUMENTATION
404181342	CORRESPONDENCE
404181353	ANALYTICAL DATA SUMMARY TABLE(S)

Total Attach: 7 Files

General Comments**User Group****Comment****Comment Date**

Environmental	Operator shall address COA from previous Supplemental Form 19: Operator's Corrective Action Report is insufficient. It is both reasonable and necessary to expect freezing temperatures in this region. Operator shall submit a detailed corrective action report explaining why this line had not failed during previous freezing periods and what is being done at this and other locations to prevent a reoccurrence at this and other locations.	05/09/2025
---------------	---	------------

Total: 1 comment(s)