

PROJ



00375296

CONTACT TRACKING

INITIALS TK DATE 10/13/93 CONTACT Brad Laney

PROBLEM: 8 5/8" casing was found sticking out of ground. Mobil volunteered to ~~be~~ plug the well. They (BEM or Mobil) had no records concerning this well. There was evidence that they had been a flow line to the well so it may have produced for some period of time

INITIALS _____ DATE _____ CONTACT _____

PROBLEM: _____

INITIALS _____ DATE ____ / ____ / ____ CONTACT _____

PROBLEM: _____

INITIALS _____ DATE ____ / ____ / ____ CONTACT _____

PROBLEM: _____

INITIALS _____ DATE ____ / ____ / ____ CONTACT _____

PROBLEM: _____

INITIALS _____ DATE ____ / ____ / ____ CONTACT _____

PROBLEM: _____