

Fulcrum
Surprise CTB
Location ID: 436676



Location



Stored equipment

Fulcrum
Surprise CTB
Location ID: 436676



Stored equipment and containment failing



Lack of containment

Fulcrum
Surprise CTB
Location ID: 436676



Stored equipment



Containment full

Fulcrum
Surprise CTB
Location ID: 436676



Staining



Stored equipment (dehy)

**Fulcrum
Surprise CTB
Location ID: 436676**



Lack of bird protection



Location crypto mining equipment

Fulcrum
Surprise CTB
Location ID: 436676



Staining



Location

Fulcrum
Surprise CTB
Location ID: 436676



Lack of calibration cards



VRU

Fulcrum
Surprise CTB
Location ID: 436676



Containment insufficient



Location



Fulcrum
Surprise CTB
Location ID: 436676



Location



Location

Fulcrum
Surprise CTB
Location ID: 436676



Location



Location

Fulcrum
Surprise CTB
Location ID: 436676



May 6, 2025 at 10:46:06 AM
+40.516100,-106.388146 ±9.17r
ECM

ECD's



May 6, 2025 at 10:50:23 AM
+40.515596,-106.387541 ±3.32r
ECM

Tote not contained and stored equipment

Fulcrum
Surprise CTB
Location ID: 436676



Debris



Gas powered generators

Fulcrum
Surprise CTB
Location ID: 436676



Gas powered generators



Gas powered generators and crypto mining buildings

Fulcrum
Surprise CTB
Location ID: 436676



May 6, 2025 at 11:01:10 AM
+40.514353,-106.386736 ±5.82r
ECM

Gas powered generators



May 6, 2025 at 11:02:32 AM
+40.514292,-106.387351 ±3.38r
ECM

Crypto mining buildings

Fulcrum
Surprise CTB
Location ID: 436676



Stored equipment



Stored equipment (compressor)