

Fulcrum
Ray Ranch CTB
Location ID: 436642

May 7, 2025 at 11:45:17 AM
+40.618269,-106.401494 ±4.75r
ECM



Location

May 7, 2025 at 11:45:33 AM
+40.618269,-106.401389 ±4.75r
ECM



Location

Fulcrum
Ray Ranch CTB
Location ID: 436642



Stored equipment



Stored equipment

Fulcrum
Ray Ranch CTB
Location ID: 436642



Lack of proper secondary containment



Lack of meter calibration card

Fulcrum
Ray Ranch CTB
Location ID: 436642




Stored equipment



Stored equipment

Fulcrum
Ray Ranch CTB
Location ID: 436642



Stored equipment open lines for wildlife to enter



Stored equipment

Fulcrum
Ray Ranch CTB
Location ID: 436642



May 7, 2025 at 12:21:06 PM
+40.617862,-106.400789 ±7.12r
ECM

Location



May 7, 2025 at 12:21:43 PM
+40.617856,-106.400534 ±3.88r
ECM

Location (crypto mining equip)

**Fulcrum
Ray Ranch CTB
Location ID: 436642**



Debris



Lack of bird protection

Fulcrum
Ray Ranch CTB
Location ID: 436642



Stored equipment