

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2025

Submitted Date:

05/13/2025

Document Number:

710500502

**FIELD INSPECTION FORM**

Loc ID 333947 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268074	WELL	PR	10/01/2023	CBM	071-07863	Torcom 33-17V	EI
270793	PIT	AC			-	TORCOM 17-33V	EI
272380	WELL	PR	02/11/2005	CBM	071-08069	Torcom 33-17R	EI
279667	PIT	AC			-	TORCOM 17-33R	EI

**General Comment:**

[This is an Environmental Inspection for the Torcom 33-17 V and Torcom 33-17 R well locations located in Las Animas County Colorado.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Well placards are located on Meter House		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Conduit for ancillary equipment is bent and extending into roadway.		
Corrective Action:	Comply with Rule 606	Date:	06/12/2025

Overall Good:

**Spills:**

Type	Area	Volume	
Produced Water	WELLHEAD		
Comment:	At the time of inspection, a packing leak was observed on the Torcom 33-17 V. ENR Foreman was notified on 5/12/2025 @ 11:54 a.m.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 05/14/2025

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 268074 Type: WELL API Number: 071-07863 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 270793 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 272380 Type: WELL API Number: 071-08069 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 279667 Type: PIT API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500503	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047900">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7047900</a>