

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404203807

Date Received:  
05/14/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:  
3 of 3 CAs from the FIR responded to on this Form  
3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10755  
Name of Operator: MORNINGSTAR OPERATING LLC  
Address: 400 W 7TH ST  
City: FORT WORTH State: TX Zip: 76102  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

**Additional Operator Contact:**

Contact Name	Phone	Email
Blaylock, Connie		cblaylock@mspartners.com
Byars, Amy		abyars@mspartners.com

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 714002044  
Inspection Date: 04/03/2025 FIR Submit Date: 04/04/2025 FIR Status:

**Inspected Operator Information:**

Company Name: MORNINGSTAR OPERATING LLC Company Number: 10755  
Address: 400 W 7TH ST  
City: FORT WORTH State: TX Zip: 76102

**LOCATION - Location ID: 320879**

Location Name: HAUSCHILD 32-5-N32N5W Number: 18NESE County:  
Qtrqtr: NESE Sec: 18 Twp: 32N Range: 5W Meridian: N  
Latitude: 37.015250 Longitude: -107.428340

**FACILITY - API Number: 05-007- -00 Facility ID: 320879**

Facility Name: HAUSCHILD 32-5-N32N5W Number: 18NESE  
Qtrqtr: NESE Sec: 18 Twp: 32N Range: 5W Meridian: N  
Latitude: 37.015250 Longitude: -107.428340

**CORRECTIVE ACTIONS:**

1 CA# 203886

Corrective Action: Update signs per rule 605a. Date: 05/04/2025

Response: CA COMPLETED Date of Completion: 05/12/2025

Operator Comment: Sign has been updated.

ECMC Decision:

ECMC Representative:

2 CA# 203887

Corrective Action: Conduct revegetation/reseeding efforts within portions of the interim reclamation area with bare soils and sparse vegetation.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 05/12/2025

Operator Comment: Reseeding has been completed.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

3 CA# 203888

Corrective Action: Comply with rule 1002f. Install or repair required BMPs. Storm water BMPs and erosion controls (ie: ecofiber, straw mulch, erosion control blankets, etc.) need to be installed and maintained on portions of the project area sparse and bare soils until soils are stabilized with desirable perennial vegetation.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 05/12/2025

Operator Comment: Area has been mulched.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 5/14/2025 3:05:36 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

Table with 2 columns: Document Number, Description. Rows include 404203807 (FIR RESOLUTION SUBMITTED) and 404203830 (Photo of sign).

Total Attach: 2 Files