

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2025

Submitted Date:

05/13/2025

Document Number:

715501695

FIELD INSPECTION FORM

Loc ID: 335747 Inspector Name: Burchett, Kirby On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 734 MAIN STREET 3RD FLOOR
City: GRAND JUNCTION State: CO Zip: 81501

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections	(970) 675-7928	inspections@utahgascorp.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231686	WELL	PR	08/19/1989	GW	103-09357	DRAGON TRAIL UNIT 1067	PR
267573	WELL	PR	11/21/2003	GW	103-10312	DRAGON TRAIL 1158X	PR

General Comment:

[ECMC Inspection Report Summary](#)

On Tuesday, 05/13/2025, Inspector Kirby Burchett, was on location for a follow up field inspection at Utah Gas Op Ltd dba Utah Gas Corp on the Dragon Trail Unit-62S101W 27SWSE pad, Location #335747, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District and Black Bear area with High Priority and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715501506 on 4/30/25. Operator submitted FIRR #404184423 on 4/30/25 addressing 3 of 3 Corrective Actions issued. The following Corrective Actions are unresolved and original due dates remain:

1. Spill staining.
2. Tank containment inadequate.

Refer to Inspection Photos for observed compliance issues.

While on location no additional compliance issues were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information: Name of Operator; Operator's emergency contact telephone number; Tank capacity; Tank contents; and NFPA label or equivalent globally harmonized label.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	
Lube Oil			
Comment:	Staining around compressor. Previous stain appears to have been covered with new soil.		
Corrective Action:	Remove and properly dispose of oily waste, stained and/or contaminated soil.		Date: <u>04/24/2025</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			

Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Wellheads		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Methanol tank on containment		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<50 BBLS	Open Top		,
Comment:	Round steel. Expanded metal top. Debris on top of tank cover.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	45
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			
Comment:	Unlined. Secondary containment is inadequate to contain 150% of the volume of the largest tank.			
Corrective Action:	Repair or install berms or other secondary containment devices.			Date: 05/09/2025

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 231686 Type: WELL API Number: 103-09357 Status: PR Insp. Status: PR

Producing Well

Comment: [February 2025 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 267573 Type: WELL API Number: 103-10312 Status: PR Insp. Status: PR

Producing Well

Comment: [February 2025 Production Report](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Drains				
				Material Handling And Spill Prevention		
		Ditches				
Berms						
Ditches						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404202838	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7048069
715501696	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7048063