

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404210935

Date Received:

05/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10417

Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC

Address: 113 N SANTA FE AVE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Harkins, Liz

lharkins@fremontpetroleum.com

Hart, Tim

309-999-5420

thart@fremontpetroleum.com

Wheeler, Steven

steven.wheeler@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 713600852

Inspection Date: 03/20/2024

FIR Submit Date: 03/22/2024

FIR Status: _____

Inspected Operator Information:

Company Name: INCREMENTAL OIL & GAS (FLORENCE) LLC

Company Number: 10417

Address: 113 N SANTA FE AVE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 417859

Location Name: Woolly Bugger

Number: 34-20

County: FREMONT

Qtrqtr: SWSE Sec: 20 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.376641 Longitude: -105.132744

FACILITY - API Number: 05-043-

-00

Facility ID: 417858

Facility Name: Woolly Bugger

Number: 34-20

Qtrqtr: SWSE Sec: 20 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.376641 Longitude: -105.132744

CORRECTIVE ACTIONS:

1 CA# 193487

Corrective Action: Submit an eForm 44 Flowline Report per Rule 1101.a.

Date: _____

Response: CA COMPLETED

Date of Completion: 03/25/2024

Operator Comment: Doc No. 403680571 filed on 3/25/2024, approved on 3/26/2024. ECMC inspection, doc no. 713601758, confirmed Form 44 filed, and CA completed.

ECMC Decision: _____

ECMC
Representative:

2 CA# 193488

Corrective Action: Comply with 1003 Interim reclamation Rules.

Date: _____

Response: CA COMPLETED

Date of Completion: 03/04/2025

Operator
Comment:

Weeds around the tank battery have been sprayed. This location was built prior to a 2A. A Rule 1003 Interim Reclamation Variance will be filed to address the Surface Owners request to keep the location in it's current size for Incremental's current operational use. The Surface Owner intends to build a residence on the location when it is no longer operational.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mackenzie Smith

Signed: _____

Title: Staff Engineer

Date: 5/20/2025 1:10:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files