

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2025

Submitted Date:

05/21/2025

Document Number:

697505934**FIELD INSPECTION FORM**Loc ID 330783 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251813	WELL	PA	07/10/2020	OW	123-19617	COLORADO ENERGY FEDERAL 14-3	RI
330783	LOCATION	AC			-	COLORADO ENERGY FEDERAL-610N64W 14NWSW	RI

General Comment:

This is a follow up Final Reclamation inspection to Field Inspection Report (FIR) Doc.# 697505430.

Inspected Facilities									
Facility ID:	251813	Type:	WELL	API Number:	123-19617	Status:	PA	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	330783	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% Fail Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Per the previous FIR, the Operator performed soil testing to investigate soil properties related to soil suitability defined in Table 915-1. Soil results indicated that the Operator imported non-compliant topsoil that would not support plant growth. Operator is to remove all non-compliant topsoil and import an approved topsoil source verified by ECMC Reclamation Staff. Once the approved topsoil source has been imported then the Operator shall perform decompaction alleviation, seed with the approved Forest Service seed mix and stabilize the seeded soil.

At the time of this inspection, the Operator has failed to initiate any further reclamation and is past the corrective action due date of 11/18/2024.

Corrective Action:

Comply with Rule 1004 as described above and submit the required FIRR per Rule 210.b. once final reclamation has been completed.

Date **11/18/2024**

Overall Final Reclamation

FailWell Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of this inspection, no stormwater erosion issues were observed.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Operator does not need to remove topsoil from the access road.	binschusc	05/21/2025
Note- there are a total of seven final reclamation locations in this area where the Operator has to remove all non-compliant topsoil and import an approved topsoil source verified by ECMC Reclamation Staff. All of the seven final reclamation location were PA'ed in 2020; therefore, all these locations are nearly five years out of compliance with Rule 1004.	binschusc	05/21/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697505935	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7059117