

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad

Location ID: 335202



Location Overview: Location is within High
Priority/Density/NSO/Black Bear Habitat areas.

Section/Township/Range: 29 6S91W



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad
Location ID: 335202



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad
Location ID: 335202



Photo # 2473 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 2474 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad
Location ID: 335202



Photo # 2475 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 2476 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad
Location ID: 335202



Photo # 2477 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 2478 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad
Location ID: 335202



Photo # 2479 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 2480 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad
Location ID: 335202



Photo # 2481 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Photo # 2482 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad
Location ID: 335202



Photo # 2483 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 2484 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT 6-29 Pad
Location ID: 335202



Photo # 2485 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 2486 Failure to minimize erosion & transport of sediment off location/insufficient BMP's