

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 2825 From entrance to location




Photo # 2826 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



May 22, 2025 at 1:37:26 PM
CO

Photo # 2827 Location



May 22, 2025 at 1:41:23 PM
CO

Photo # 2828 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 2829 Location




Photo # 2830 Location

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 2831 Location



Photo # 2832 PRV vent line does not comply with CECMC pressure safety device rules or general safety rules

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 623 From inspection 708906247 conducted on 04/10/2025 Tank is disconnected & not in use/unused equipment



Photo # 2833 Tank is disconnected & not in use/unused equipment

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 624 From inspection 708906247 conducted on 04/10/2025 Tank is disconnected & not in use/unused equipment



Photo # 2834 Tank is disconnected & not in use/unused equipment

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 625 From inspection 708906247 conducted on 04/10/2025 Tank is disconnected & not in use/unused equipment



Photo # 2835 Tank is disconnected & not in use/unused equipment

Inspection/Audit Photos

Location Name: TEP Rocky Mountain LLC GIBSON GULCH UNIT 12-28 Pad

Location # 335266



Photo # 626 From inspection 708906247 conducted on 04/10/2025 Tank is disconnected & not in use/unused equipment



Photo # 2836 Tank is disconnected & not in use/unused equipment