

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 116-33 Pad

Location ID: 334780



Photo # 3438 From entrance to location




Photo # 3439 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 116-33 Pad

Location ID: 334780



Photo # 3440 Location



Photo # 3441 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 116-33 Pad

Location ID: 334780



Photo # 3442 Location



Photo # 3443 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 116-33 Pad

Location ID: 334780




Photo # 3444 Location



Photo # 3445 Unmarked deadman

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 116-33 Pad

Location ID: 334780



Photo # 3446 Same unmarked deadman



Photo # 3447 Same unmarked deadman

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 116-33 Pad

Location ID: 334780



Photo # 3448 Improperly marked deadman



Photo # 3449 Same improperly marked deadman

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 116-33 Pad

Location ID: 334780



May 27, 2025 at 10:52:13 AM  
CO



May 27, 2025 at 10:52:39 AM  
CO

Photo # 3450 Stored truck & tractor in the interim area

Photo # 3451 Stored vehicles in the interim area

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 116-33 Pad

Location ID: 334780



Photo # 3452 Stored vehicles & tractor in the interim area



Photo # 3453 Stored truck in the interim area & debris on the ground near truck

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RMV 116-33 Pad

Location ID: 334780




Photo # 3454 Tank label missing required information