

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404219547

Date Received:

05/28/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Walker, Mandi

mwalker@hilcorp.com

, General

FarmingtonRegulatoryTechs@hilcorp.com

Shorty, Priscilla

505-324-5188

pshorty@hilcorp.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002170

Inspection Date: 05/13/2025

FIR Submit Date: 05/20/2025

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333494

Location Name: ARGENTA 34-10-M34N10W Number: 32NWSE County: _____

Qtrqtr: NWSE Sec: 32 Twp: 34N Range: 10W Meridian: M

Latitude: 37.144480 Longitude: -107.954750

FACILITY - API Number: 05-067- -00 Facility ID: 333494

Facility Name: ARGENTA 34-10-M34N10W Number: 32NWSE

Qtrqtr: NWSE Sec: 32 Twp: 34N Range: 10W Meridian: M

Latitude: 37.144480 Longitude: -107.954750

CORRECTIVE ACTIONS:

1 CA# 204948

Corrective Action: Comply with rule 606. Remove unused oil and gas equipment and debris.

Date: 06/03/2025

Response: CA COMPLETED

Date of Completion: 05/27/2025

Operator Comment: Removed unused muffler equipment at pumpjack and cable debris in the western portion of the interim reclamation area. See attached photos.

ECMC Decision: _____

ECMC
Representative:

2 CA# 204949

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 1002.

Date: 05/27/2025

Response: CA COMPLETED

Date of Completion: 05/27/2025

Operator
Comment:

Repaired leaks and removed stained soil and disposed of it properly. See attached photos.

ECMC Decision: _____

ECMC
Representative:

3 CA# 204950

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 05/27/2025

Response: CA COMPLETED

Date of Completion: 05/27/2025

Operator
Comment:

Marked guy line anchor. See attached photos.

ECMC Decision: _____

ECMC
Representative:

4 CA# 204951

Corrective Action: Comply with rule 1002f.

Date: _____

Response: CA COMPLETED

Date of Completion: 05/27/2025

Operator
Comment:

All erosion issues have been addressed properly. See attached photos.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 5/28/2025 10:08:16 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404219556	Argenta 34-10 32-2_714002170 Resolved Photos

Total Attach: 1 Files