

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET
DENVER, COLORADO 80203
(303) 894-2109 FAX
(303) 894-2100



DENNIS R. BICKNELL
Director
JOHN R. STOWELL
Deputy Director
PATRICIA C. BEAVER
Technical Secretary

ROY ROMER
Governor

DATE: DEC 18 1991

TIMKA RESOURCES
4317 WHIPPNEY
FT COLLINS CO 80526

Lease: STATE #1
Location: SENE 15-10N-53W
County: LOGAN

Gentlemen:

The indicated lease(s) were inspected on the date shown below and the following conditions were observed to exist at the time of the inspection.

- | | |
|---|--|
| <input type="checkbox"/> Oil accumulation in retaining pit(325) | <input type="checkbox"/> Thief Hatch Open(604.a(9)) |
| <input type="checkbox"/> Skim pit needs repair(Rule 325) | <input type="checkbox"/> Loose Fittings(604.d) |
| <input type="checkbox"/> Skim tank/pit required(325) | <input type="checkbox"/> Bradenhead Access(Order A-1-3) |
| <input type="checkbox"/> Well sign required (210.a,604.c) | <input type="checkbox"/> Berms Inadequate(604.a(4)) |
| <input type="checkbox"/> Oil spilled at wellhead or battery | <input type="checkbox"/> Weeds, debris or waste material observed at site(603.g) |
| <input checked="" type="checkbox"/> Abandonment work incomplete | <input type="checkbox"/> Other(see Remarks) |

REMARKS: 3 bolted tanks, pits and treater remain at the site. Please notify when removed, Must be removed within 6 months of plugging.

The above violation(s) should be corrected immediately and a written report submitted to this office within thirty (30) days after the work is accomplished, advising us of the date and manner of correction. Any accumulation of oil in the retaining pits must be removed within ten (10) days after receipt of this notice (Rule 325).

Per call to Timka, PA
OK

Robert J. Van Sickle
Robert J. Van Sickle
Field Engineer

Date of Inspection: 10-25-91