

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2025

Submitted Date:

05/30/2025

Document Number:

697602531

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
Brown, Kari		kari.oakman@state.co.us	
,		cogcc@kpk.com	All Inspections
Kirschner, Steven		steven.kirschner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479713	SPILL OR RELEASE	CL	07/28/2021		-	Camenisch 1 sx Flowline Release	EI
482375	SPILL OR RELEASE	CL	09/12/2022		-	Camenisch 1sx New Release	EI

General Comment:

ECMC Environmental Inspection to determine progress on the Camenisch 1 sx Flowline Release (Spill ID 479713 & 482375/Remediation Project No 18954). Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 479713 & 482375
Spill Name: Camenisch 1 sx Flowline Release & Camenisch 1sx New Release
Reported Date of Discovery: 3/29/2021 & 6/9/2022

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weed are overgrown throughout the location including at the tank battery and around and within the excavation.		
Corrective Action:	Comply with housekeeping Rule 606.	Date:	06/06/2025
Type	TRASH		
Comment:	Trash was observed within the excavation.		
Corrective Action:	Comply with housekeeping Rule 606.	Date:	06/06/2025

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Barbed wire fencing surrounding the excavation is adequate tp prevent access.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 479713 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482375 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: The last Form 27 Supplemental was submitted on 8/28/2023. Operator has not submitted a form within the approved quarterly reporting schedule and Rule 913.e.(3); the next quarterly report was due 11/28/2023.

Corrective Action: Operator shall immediately submit a Form 27 for Remediation Project 18954 that includes a specific workplan and timeline to address the remaining impacts. Date: 11/28/2023

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: The excavation remains open. No remedial work has been done since the last inspection. Weeds have overgrown throughout the entire location due to lack of progress.

Corrective Action: Operator will comply with the implementation schedule and Conditions of Approval for all remaining remediation of soil impacts, reclamation, and reporting established in the ECMC Remediation Project No. 18954. Date: _____

In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
Site is in poor condition. No visible work has been completed since the last inspection. Operator has not submitted a Form 27 Remediation Workplan since 8/28/2023 in violation of quarterly reporting requirements. Operator shall respond immediately to address the poor site conditions and remaining remediation project that includes a specific workplan and timeline to address the remaining impacts.	ahmadiaa	05/30/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602532	Photolog	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7075849