

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404224418

Date Received:
05/30/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10670
Name of Operator: BISON IV OPERATING LLC
Address: 518 17TH STREET SUITE 1800
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Jenkins, Steve		ops@bisonog.com
Chris Binschus		steve.jenkins@state.co.us
		chris.binschus@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 697505904
Inspection Date: 05/13/2025 FIR Submit Date: 05/13/2025 FIR Status:

Inspected Operator Information:

Company Name: BISON IV OPERATING LLC Company Number: 10670
Address: 518 17TH STREET SUITE 1800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 422671

Location Name: Wagner Number: 11-65 9-1H County:
Qtrqtr: NW Sec: 9 Twp: 11N Range: 65W Meridian: 6
NE
Latitude: 40.940802 Longitude: -104.664777

FACILITY - API Number: 05-123-00 Facility ID: 422671

Facility Name: Wagner Number: 11-65 9-1H
Qtrqtr: NW Sec: 9 Twp: 11N Range: 65W Meridian: 6
NE
Latitude: 40.940802 Longitude: -104.664777

CORRECTIVE ACTIONS:

1 CA# 204752

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 05/30/2025

Response: CA COMPLETED

Date of Completion: 05/30/2025

Operator
Comment:

As requested, Bison has completed reseeding in line with the following Corrective Action:

Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

Attn: Chris Binschus

Unable to add 'desc' for photos and cannot submit without dropdown reference. Therefore, pictures will be sent in a follow up email.

Apologies.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tarah Garza

Signed: _____

Title: Env Compliance Specialist

Date: 5/30/2025 5:20:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files