

TEP
KP 22-21
Location ID: 335209



Location



Location

TEP
KP 22-21
Location ID: 335209



Location



Location

TEP
KP 22-21
Location ID: 335209



Location/ 1 well sign still illegible



Location

TEP
KP 22-21
Location ID: 335209



Lines capped



PRV taped still facing unsafe direction.

TEP
KP 22-21
Location ID: 335209



Staining



Culvert at entrance is becoming silted off