

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/07/2025

Submitted Date:

05/23/2025

Document Number:

712300119

FIELD INSPECTION FORM

Loc ID: 467526
Inspector Name: Maxwell, Logan
On-Site Inspection:
2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Findings:
6 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		aaron.trujillo@state.co.us	
		j75rober@blm.gov	
		annalee@fulcrumef.com	
		inspections@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467526	LOCATION	AC			-	Spicer S32 Annex Pad	RI

General Comment:
On 05/07/2025, Reclamation Specialist Maxwell conducted an Interim Reclamation and Stormwater inspection at Fulcrum Energy Operating's Spicer S32 Annex Pad Oil and Gas Location in Jackson County, Colorado.
This inspection is a follow-up to #712300070 dated 9/10/2024, to document compliance with the following corrective actions:
-Weeds
-Interim Reclamation
Please note: On 9/10/2024, Inspection #712300070 was conducted at the Spicer S32 Annex, Location ID: 467526, not the Spicer Pad, Location ID: 324574. All corrective actions and comments from the previous inspection that have not been addressed are applicable to the Spicer Annex pad.
Refer to the "Location," and "Reclamation" sections of this inspection report for additional details.
Refer to the photo-documentation of the observed compliance issues attached to this report.
Any corrective actions from previous inspections that have not been addressed remain applicable. Any new corrective actions without corrective action dates, requires that the Operator comply with the Rules as soon as possible or when environmental conditions permit. Location will remain out of compliance until corrective action(s) has (have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment:

At the time of this inspection, weeds were not observed along the perimeter edges. Continue to monitor and manage weeds.

This corrective action has been resolved.

Corrective Action:

Date:

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Bird Protectors

#

Comment:

It was observed that the secondary containment for the tanks have not been properly covered to prevent access by wildlife, including birds and bats.

Corrective Action:

Comply with Rule 902.b.- install covers or other BMPs to prevent wildlife access to the tank equipment.

Date: 06/11/2025

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 467526 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment *It was observed in this inspection that the topsoil pile was stabilized with erosion matting.*

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment It appears that seeding has occurred and straw mulch has been applied to the interim reclamation area. Straw mulch has accumulated densely in some areas and blown off in other areas. Monitor the interim area for germination and plant growth. It is unclear if all areas not needed for production have been interim reclaimed.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of this inspection, no stormwater erosion issues were observed at this Location or along the access road.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712300129	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7081714