

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MCLAUGHLIN-66S92W/27SENE

Location ID: 335082

Date: 6/5/2025



Location – Photo #09145

Location – Photo #09141

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MCLAUGHLIN-66S92W/27SENE

Location ID: 335082

Date: 6/5/2025



Location – Photo #09143



Location – Photo #09144

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MCLAUGHLIN-66S92W/27SENE

Location ID: 335082

Date: 6/5/2025



Location – Photo #09152



Location – Photo #09158

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MCLAUGHLIN-66S92W/27SENE

Location ID: 335082

Date: 6/5/2025



Location – Photo #09142



Illegible Wellhead Sign – Photo #09146

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MCLAUGHLIN-66S92W/27SENE

Location ID: 335082

Date: 6/5/2025



Illegible Wellhead Sign – Photo #09147

Illegible Wellhead Sign – Photo #09148

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MCLAUGHLIN-66S92W/27SENE

Location ID: 335082

Date: 6/5/2025



Illegible Wellhead Sign – Photo #09149



Illegible Wellhead Sign – Photo #09150

Audit Photos


Location Name: TEP ROCKY MOUNTAIN LLC, MCLAUGHLIN-66S92W/27SENE

Location ID: 335082

Date: 6/5/2025



Illegible Wellhead Sign – Photo #09151



PRV Terminates in Unsafe Manner – Photo #09157

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MCLAUGHLIN-66S92W/27SENE

Location ID: 335082

Date: 6/5/2025



PRV Terminates in Unsafe Manner – Photo #09159

PRV Terminates in Unsafe Manner – Photo #09160