



Martin T. Hart Unit | 1  
© 21-May-25 10:50:45 AM  
ECMC Environmental Inspection

Approximate spill location.



WGS84 40.11087, -104.86531  $\Delta^m_{\pm 3m}$  1516  $\triangle^{\circ,T}_{\pm 11}$  E78



ECMC  
Environmental  
Field Inspection



Martin T. Hart Unit 1 1  
© 21-May-25 10:51:37 AM  
ECMC Environmental Inspection



WGS84 40.11081, -104.86517  $\Delta$   $\pm 11$ ft  $\pm 3$ m 1516  $\angle$   $\pm 11$  °,T NW340



ECMC  
Environmental  
Field Inspection



Martin T. Hart Unit I 1  
© 21-May-25 10:51:54 AM  
ECMC Environmental Inspection

Emergency contact number is visible at the wellhead.



WGS84 40.11089, -104.86635  $\Delta$   $\pm 9\text{ft}$   $\pm 3\text{m}$  1518  $\triangle$   $\pm 11$  °,T SW244



ECMC  
Environmental  
Field Inspection



Martin T. Hart Unit I 1  
© 21-May-25 10:53:10 AM  
ECMC Environmental Inspection

Weeds are visible throughout the location.









Martin T. Hart Unit I 1  
© 21-May-25 10:54:03 AM  
ECMC Environmental Inspection

Signage not updated to reflect current Operator is visible.





Signage with emergency contact number is visible at the tank battery.



WGS84  $\pm 10\text{ft}$  40.11071, -104.86716  $\Delta^m_{\pm 3\text{m}}$  1518  $\triangle^{\circ, T}_{\pm 11}$  NE70



ECMC  
Environmental  
Field Inspection



Martin T. Hart Unit 1 1  
© 21-May-25 10:55:08 AM  
ECMC Environmental Inspection