

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2025

Submitted Date:

06/12/2025

Document Number:

717900217

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Robinson, Taylor On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kari Brown		kari.brown@state.co.us	
Nikki Graber		nikki.graber@state.co.us	
Kauffman, KPK		cogcc@kpk.com	All Inspections
Ross Watzman		rwatzman@kpk.com	

General Comment:

This is an environmental inspection for Spill ID 487690 Rasmussen Flowline. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: The access road is in good condition but the area to the East where it appears the operator spread fill material is inundated with weeds.

Corrective Action:

Date:

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment: This inspection was in response to a previous spill. The spill has since been cleaned up but remediation is ongoing.

Multiple Spills and Releases?

Fencing/:

Type

Comment: No fencing present.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Location Construction

Location ID: 487690 CDP: _____

Comment:

Corrective Action:

Date: _____

Form 2A COAs:

Comment:

Corrective Action:

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Comment:

Corrective Action:

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: This inspection was in response to a precious spill that has since been cleaned up. Remediation is ongoing. There was one monitoring well on site, however, it was not capped and is therefore exposed to potential outside contamination. Monitoring wells were observed on location without proper caps/plugs. Operator shall install j-plugs in all monitoring wells.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

ECMC Comments

Comment	User	Date
This spill is currently being referred to enforcement.	robinsotl	06/10/2025
Monitoring wells were observed on location without proper caps/plugs. Operator shall install j-plugs in all monitoring wells.		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717900218	photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093597