

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 16-4 PAD

Location ID: 324465

Date: 06/11/2025



Photo # 8323 Entrance to location



Photo # 8324 Location

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 16-4 PAD

Location ID: 324465

Date: 06/11/2025



Photo # 8325 Emergency Contact Number is not in service, additionally quarter/quarter section is becoming illegible



Photo # 8388 Emergency Contact Number is not in service, additionally quarter/quarter section is becoming illegible

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 16-4 PAD

Location ID: 324465

Date: 06/11/2025



Photo # 8390 Emergency Contact Number is not in service

Photo # 8353 Location



Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 16-4 PAD

Location ID: 324465

Date: 06/11/2025



Photo # 8360 Location



Photo # 8374 Location

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 16-4 PAD

Location ID: 324465

Date: 06/11/2025



Photo # 8387 Location



Photo # 8395 NW corner of location



Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 16-4 PAD

Location ID: 324465

Date: 06/11/2025



Photo # 8396 NE corner of location



Photo # 8397 SE corner of location

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 16-4 PAD

Location ID: 324465

Date: 06/11/2025



Photo # 8398 SW corner of location



Photo # 8330 Bradenhead leak

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 16-4 PAD

Location ID: 324465

Date: 06/11/2025



Photo # 8354 Chemical tank lacks required labeling/not in compliance with CECMC rules



Photo # 8371 PRV vent line does not comply with CECMC pressure safety device rules