

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404241311

Date Received:

06/16/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10755

Name of Operator: MORNINGSTAR OPERATING LLC

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Connie Blaylock

cblaylock@mspartners.com

abyars@mspartners.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002118

Inspection Date: 04/28/2025

FIR Submit Date: 05/01/2025

FIR Status: _____

Inspected Operator Information:

Company Name: MORNINGSTAR OPERATING LLC

Company Number: 10755

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

LOCATION - Location ID: 334035

Location Name: QUINTANA 32-6-N32N6W Number: 15SWSE County: _____

Qtrqtr: SWSE Sec: 15 Twp: 32N Range: 6W Meridian: N

Latitude: 37.011380 Longitude: -107.486180

FACILITY - API Number: 05-067- -00 Facility ID: 334035

Facility Name: QUINTANA 32-6-N32N6W Number: 15SWSE

Qtrqtr: SWSE Sec: 15 Twp: 32N Range: 6W Meridian: N

Latitude: 37.011380 Longitude: -107.486180

CORRECTIVE ACTIONS:

1 CA# 204537

Corrective Action: Update signs per rule 605a.

Date: 06/01/2025

Response: CA COMPLETED

Date of Completion: 05/26/2025

Operator
Comment: Sign corrected.

ECMC Decision: _____

ECMC Representative:			
----------------------	--	--	--

2	CA# 204538		
Corrective Action:		Conduct revegetation/reseeding efforts within portions of the interim reclamation area with bare soils and sparse vegetation.	Date: <u>05/15/2025</u>
Response:		CA COMPLETED	Date of Completion: <u>06/14/2025</u>
Operator Comment:		Area reseeded as of 6/14 - was delayed due to rain.	
ECMC Decision:			
ECMC Representative:			

3	CA# 204539		
Corrective Action:		Erosion controls need to be installed and maintained until bare soils are stabilized with desirable perennial vegetation. Comply with rule 1002 Install or repair required BMPs.	Date: _____
Response:		CA COMPLETED	Date of Completion: <u>05/26/2025</u>
Operator Comment:		Erosion controls in place.	
ECMC Decision:			
ECMC Representative:			

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock Signed: _____

Title: Regulatory Analyst Date: 6/16/2025 8:30:31 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404241311	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files