

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2025

Submitted Date:

06/20/2025

Document Number:

718100607

FIELD INSPECTION FORM

Loc ID: 324292 Inspector Name: Trujillo, Aaron On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324292	LOCATION	AC			-	CC 0605-13-22 Pad	RI

General Comment:

On 6/18/2025, Western Reclamation Work Lead Trujillo conducted an interim reclamation inspection at Laramie Energy LLC's CC/0605-13-22 Pad location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Interim Reclamation
- Wildlife protections

Refer to the Location and Reclamation sections of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Location Entrance		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	#		
Comment:	<p>It was observed in this inspection that the cellar at the well has either not been backfilled, or properly covered to prevent access by people or wildlife. Cellar has also filled with fluids.</p> <p>Rodent mortality within the cellar is evident.</p>		
Corrective Action:	Remove and properly dispose fluids within cellar, and comply with Rule 902.b	Date:	07/04/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				Adequate
Comment:	Containment BMP appeared to be in proper functioning condition at time of inspection.			
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 324292 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment **Reclamation pursuant to Rule 1003 has not been performed at this Location. Reclamation Specialist was unable to identify or locate topsoil stored on the Location for future reclamation efforts. Pursuant to Rule 1003.b.(2), Operators shall mark or document stockpile locations to facilitate subsequent reclamation efforts.**

Corrective Action **Operator shall provide documentation and figures showing the location of where the topsoil is being stored for reclamation efforts, and how much (cu. yards).
Submit documentation to Reclamation Specialist attached to a Form 4 Sundry**

Date **06/27/2025**

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? Fail
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
 Production areas have been stabilized? _____ Segregated soils have been replaced? Fail

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment It was observed in this inspection that interim reclamation pursuant to 1003 Rules has not been performed on the Location; based on a review of historic aerial imagery, Location remains unchanged since the site was constructed and the well drilled. There are areas on the south end of the Location that are not necessary for production; that have not been decompacted, the soils have not been recontoured/regraded to their relative positions/contour, topsoil has not been replaced and areas revegetated.

Corrective Action Comply with 1003 Rules. Date _____

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: <input type="text"/>	Date <input type="text"/>	
Overall Final Reclamation <input type="checkbox"/>	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718100608	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7105090