

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404250873

Date Received:
06/22/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10417
Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC
Address: 113 N SANTA FE AVE
City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Harkins, Liz	719-429-4513	Lharkins@fremontpetroleum.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 716300948
Inspection Date: 05/09/2025 FIR Submit Date: 05/09/2025 FIR Status:

Inspected Operator Information:

Company Name: INCREMENTAL OIL & GAS (FLORENCE) LLC Company Number: 10417
Address: 113 N SANTA FE AVE
City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 415851

Location Name: DOLLY VARDEN Number: 41-20 County: FREMONT
Qtrqtr: NENE Sec: 20 Twp: 19S Range: 69W Meridian: 6
Latitude: 38.385801 Longitude: -105.127318

FACILITY - API Number: 05-043-00 Facility ID: 415854

Facility Name: DOLLY VARDEN Number: 41-20
Qtrqtr: NENE Sec: 20 Twp: 19S Range: 69W Meridian: 6
Latitude: 38.385801 Longitude: -105.127318

CORRECTIVE ACTIONS:

1 CA# 204684

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D Date: 05/21/2025

Response: CA COMPLETED Date of Completion: 05/09/2025

Operator Comment: Recent oil haulage by contract Oil Haulers have occurred during nighttime hours and resulted in oil impacted soil at tank valve. Operator took corrective actions on May 9, 2025 to remove the impacted soil and replace with clean, fresh soil. Attachment is a photo of replaced, damp, fresh soil at back of tank.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Actions were undertaken on 5/09/25 to replace impacted soil behind tank at tank battery and replace with fresh soil.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Liz Harkins

Signed: _____

Title: Engineer

Date: 6/22/2025 7:28:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

404250874	RESPONSE PHOTOS
-----------	-----------------

Total Attach: 1 Files