

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404250873

Date Received:  
06/22/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10417  
Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC  
Address: 113 N SANTA FE AVE  
City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Harkins, Liz</u>	<u>719-429-4513</u>	<u>Lharkins@fremontpetroleum.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 716300948  
Inspection Date: 05/09/2025 FIR Submit Date: 05/09/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: INCREMENTAL OIL & GAS (FLORENCE) LLC Company Number: 10417  
Address: 113 N SANTA FE AVE  
City: FLORENCE State: CO Zip: 81226

**LOCATION** - Location ID: 415851

Location Name: DOLLY VARDEN Number: 41-20 County: FREMONT  
Qtrqtr: NENE Sec: 20 Twp: 19S Range: 69W Meridian: 6  
Latitude: 38.385801 Longitude: -105.127318

**FACILITY** - API Number: 05-043-00 Facility ID: 415854

Facility Name: DOLLY VARDEN Number: 41-20  
Qtrqtr: NENE Sec: 20 Twp: 19S Range: 69W Meridian: 6  
Latitude: 38.385801 Longitude: -105.127318

**CORRECTIVE ACTIONS:**

**1** CA# 204684

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D Date: 05/21/2025

Response: CA COMPLETED Date of Completion: 05/09/2025

Operator Comment: Recent oil haulage by contract Oil Haulers have occurred during nighttime hours and resulted in oil impacted soil at tank valve. Operator took corrective actions on May 9, 2025 to remove the impacted soil and replace with clean, fresh soil. Attachment is a photo of replaced, damp, fresh soil at back of tank.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Actions were undertaken on 5/09/25 to replace impacted soil behind tank at tank battery and replace with fresh soil.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Liz Harkins

Signed: \_\_\_\_\_

Title: Engineer

Date: 6/22/2025 7:28:15 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404250873	FIR RESOLUTION SUBMITTED
404250874	RESPONSE PHOTOS

Total Attach: 2 Files