




RAT Observation

- No Observed Source Material (2700)
- Possible Source Material (310)
- Source Material Observed (2)





T069 AG - ECE LAND LLC - 4627 W 20TH STREET RD STE A
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Observation

Oiling Observation: 0 No Observable Oil | Id: 526246 | 4/22/2025 11:01:22 AM
(40.498224, -104.596785)
No Product





T069 AG - ECE LAND LLC - 4627 W 20TH STREET RD STE A
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 527525 | 4/22/2025 11:01:49 AM
(40.499543, -104.594611)

No visible oil on topsoil or vegetation. Tilled soil would make oil difficult to see.





T069 AG - ECE LAND LLC - 4627 W 20TH STREET RD STE A
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 526916 | 4/22/2025 1:22:56 PM
(40.496028, -104.597226)
No contamination observed on top soil.





T069 AG - ECE LAND LLC - 4627 W 20TH STREET RD STE A
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 526258 | 4/22/2025 1:39:31 PM
(40.49492, -104.593554)
No Product





T069 AG - ECE LAND LLC - 4627 W 20TH STREET RD STE A
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC
Incident Date April 7, 2025
City Galeton, CO
County Weld

Oiling Observation: 0 No Observable Oil | Id: 524522 | 4/22/2025 1:39:48 PM
(40.495936, -104.593383)
No contamination observed on top soil.





T069 AG - ECE LAND LLC - 4627 W 20TH STREET RD STE A
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **1 Possible Oil** | Id: 526692 | 4/22/2025 3:29:56 PM
(40.503358, -104.590762)

Possible contamination due to proximity of site. Dried pond. Burned vegetation.



Oiling Observation: **1 Possible Oil** | Id: 527474 | 4/22/2025 3:37:54 PM
(40.502363, -104.589732)

In the pond, SW corner walking E towards incident site. Possible product residue hard to determine. Dead fish and burned vegetation present. Habitat present





T069 AG - ECE LAND LLC - 4627 W 20TH STREET RD STE A
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **1 Possible Oil** | Id: 527745 | 4/22/2025 3:39:32 PM
(40.503764, -104.589672)

Possible contaminants on topsoil of lake





T069 AG - ECE LAND LLC - 4627 W 20TH STREET RD STE A
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **1 Possible Oil** | Id: 527805 | 4/22/2025 3:41:56 PM
(40.50372, -104.59049)

Possible contaminants on topsoil of lake





T069 AG - ECE LAND LLC - 4627 W 20TH STREET RD STE A
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **1 Possible Oil** | Id: 526634 | 4/22/2025 3:42:02 PM
(40.50392, -104.590606)

Possible contamination due to proximity of site. Dried pond. Burned vegetation

