




**RAT Observation**

- No Observed Source Material (62)
- Possible Source Material (1)
- Source Material Observed (0)





T024 AG - GEBAUER STUART L - 36095 CR 53 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

**Observation**

Oiling Observation: 0 No Observable Oil | Id: 553642 | 5/21/2025 11:03:19 AM  
(40.523559, -104.565222)  
No contamination noted, no odor noted





T024 AG - GEBAUER STUART L - 36095 CR 53 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 553464 | 5/21/2025 11:04:27 AM  
(40.523236, -104.564774)  
no visual impact, north of bishop well





T024 AG - GEBAUER STUART L - 36095 CR 53 WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: 0 No Observable Oil | Id: 553633 | 5/21/2025 11:06:18 AM  
(40.523067, -104.565245)  
No contamination noted, no odor noted





T024 AG - GEBAUER STUART L - 36095 CR 53 WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: 0 No Observable Oil | Id: 553452 | 5/21/2025 11:08:51 AM  
(40.522616, -104.564764)  
Habitat, no visual impact, north of bishop well





T024 AG - GEBAUER STUART L - 36095 CR 53 WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: 0 No Observable Oil | Id: 553638 | 5/21/2025 11:14:15 AM  
(40.524559, -104.564875)  
No contamination noted, no odor noted





T024 AG - GEBAUER STUART L - 36095 CR 53 WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: 0 No Observable Oil | Id: 553636 | 5/21/2025 11:15:58 AM  
(40.524621, -104.56478)  
No contamination noted, no odor noted





T024 AG - GEBAUER STUART L - 36095 CR 53 WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: 0 No Observable Oil | Id: 553640 | 5/21/2025 11:17:00 AM  
(40.525052, -104.564881)  
No contamination noted, no odor noted



Oiling Observation: 0 No Observable Oil | Id: 553443 | 5/21/2025 11:18:23 AM  
(40.526046, -104.564832)

No product seen at the location. Grass shows no evidence of staining nor misting and has no oily texture. Surface layer of topsoil does not show any signs of staining. No hydrocarbon scent is present. Swab of metal post shows no evidence of staining nor oily texture. Habitat vegetation at location.





T024 AG - GEBAUER STUART L - 36095 CR 53 WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: 0 No Observable Oil | Id: 553449 | 5/21/2025 11:18:52 AM  
(40.52564, -104.564857)

No visual impact, north of bishop well





T024 AG - GEBAUER STUART L - 36095 CR 53 WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: **1 Possible Oil** | Id: 553427 | 5/21/2025 11:02:54 AM  
(40.523486, -104.565562)  
Slight staining noticeable on grass

