

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404173457

Date Received:
06/27/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Steffy Goncalves		sgoncalves@cogc.com
Jeremy Wagner		jwagner@cogc.com
Bob Redweik		bredweik@cogc.com
CITATION		ENV-CODNR@cogc.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713602067
Inspection Date: 04/09/2025 FIR Submit Date: 04/14/2025 FIR Status:

Inspected Operator Information:

Company Name: CITATION OIL & GAS CORP Company Number: 17180
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

LOCATION - Location ID: 381172

Location Name: MCCORMICK 31-3-614S49W Number: 3NWNE County:
Qtrqtr: NWNE Sec: 3 Twp: 14S Range: 49W Meridian: 6
Latitude: 38.863292 Longitude: -102.873558

FACILITY - API Number: 05-017-00 Facility ID: 381172

Facility Name: MCCORMICK 31-3-614S49W Number: 3NWNE
Qtrqtr: NWNE Sec: 3 Twp: 14S Range: 49W Meridian: 6
Latitude: 38.863292 Longitude: -102.873558

CORRECTIVE ACTIONS:

1 CA# 204112

Corrective Action: Comply with 1004 Rules Date:
Response: CA COMPLETED Date of Completion: 06/25/2025

Wood debris and cement blocks have been removed for the location. Potential soil impacts are being investigated under a Form 19 Spill (ID 489932). There is not enough soil moisture to successfully complete reclamation on

Operator Comment: the areas requiring revegetation. Seeding at this time will result in wasted efforts and materials and should be completed in the Fall of 2025. In preparation for Fall 2025 reclamation, bare soil areas are stabilized, and a topsoil compost mixture was spread across the surface. Fencing will be installed around these areas to protect from further degradation from livestock. Within the Fall seeding window, decompaction will be completed and after the seedbed has been prepared, seed will be applied, and covered with crimped a straw mulch. Photos of the current location status are provided in Attachment A.

ECMC Decision: _____

ECMC Representative:

2 CA# 204113

Corrective Action:

Date: _____

Response: CA COMPLETED

Date of Completion: 06/25/2025

Operator Comment: Road base has been removed at several areas along the former access road location and used to recontour the gullies and rills along the road. The former cut slope on the east side of the former location was filled and covered with a topsoil and compost mixture to match pre-existing contour. Synthetic wattles were installed upgradient to protect from stormwater run-on. The bare soil area, north of the former pumpjack location, mentioned in ECMC reports was recontoured, and protected from erosion with an earthen berm. The bare soil area at the former pumpjack location was also covered with a topsoil and compost mixture that provides a roughened surface that will temporarily protect from erosion. The location is now in compliance and with rule 1002.f.(2). Photos of the current location status are provided in Attachment A.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joel Mason

Signed: _____

Title: Agent

Date: 6/27/2025 3:28:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404260127	Photo Documentation

Total Attach: 1 Files