



**RAT Observation**

- No Observed Source Material (15)
- Possible Source Material (0)
- Source Material Observed (0)



T007 AG - PEARSON LINDSAY - 24825 1ST ST WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

**Observation**

Oiling Observation: **0 No Observable Oil** | Id: 542516 | 5/5/2025 9:06:15 AM  
(40.523, -104.586057)  
Fencing on north end of property.





T007 AG - PEARSON LINDSAY - 24825 1ST ST WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: 0 No Observable Oil | Id: 542518 | 5/5/2025 9:11:28 AM  
(40.522851, -104.585988)  
Fencing on north end of property.





T007 AG - PEARSON LINDSAY - 24825 1ST ST WELD  
Photo Log | Rapid Assessment Technique (RAT)

**Incident** Bishop LOC  
**Incident Date** April 7, 2025  
**City** Galeton, CO  
**County** Weld

Oiling Observation: 0 No Observable Oil | Id: 542519 | 5/5/2025 9:16:14 AM  
(40.52303, -104.585943)  
Carport on east side of residence.





T007 AG - PEARSON LINDSAY - 24825 1ST ST WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 542853 | 5/5/2025 11:42:10 AM  
(40.522799, -104.586487)  
No presence of contamination found





T007 AG - PEARSON LINDSAY - 24825 1ST ST WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident	Bishop LOC
Incident Date	April 7, 2025
City	Galeton, CO
County	Weld

Oiling Observation: 0 No Observable Oil | Id: 542807 | 5/5/2025 11:43:16 AM  
(40.522912, -104.586175)  
No visible product. No odor.





T007 AG - PEARSON LINDSAY - 24825 1ST ST WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 542990 | 5/5/2025 11:44:14 AM  
(40.523062, -104.585951)  
No presence of contamination found.



Oiling Observation: 0 No Observable Oil | Id: 542957 | 5/5/2025 11:44:22 AM  
(40.522853, -104.586214)  
No indication of contamination.





T007 AG - PEARSON LINDSAY - 24825 1ST ST WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 542816 | 5/5/2025 11:44:46 AM  
(40.522821, -104.58606)  
No visible product. No odor.





T007 AG - PEARSON LINDSAY - 24825 1ST ST WELD  
Photo Log | Rapid Assessment Technique (RAT)

<b>Incident</b>	Bishop LOC
<b>Incident Date</b>	April 7, 2025
<b>City</b>	Galeton, CO
<b>County</b>	Weld

Oiling Observation: 0 No Observable Oil | Id: 542815 | 5/5/2025 11:45:31 AM  
(40.522746, -104.586293)  
No visible product. No odor.





T007 AG - PEARSON LINDSAY - 24825 1ST ST WELD  
Photo Log | Rapid Assessment Technique (RAT)

**Incident** Bishop LOC  
**Incident Date** April 7, 2025  
**City** Galeton, CO  
**County** Weld

Oiling Observation: 0 No Observable Oil | Id: 542854 | 5/5/2025 11:47:14 AM  
(40.52313, -104.58612)  
No presence of contamination found

